



Resolved CPRs

CAMWorks 2020 SP5.1

* Please refer to 'What's New' PDF document for details regarding enhancements in CAMWorks 2020.

Sr. No.	CPR Number	Help Desk ID	Area	Description
1.	CW-104739	CSR-14388	Feature	In Mill assemblies, when Extract Machinable Features command is executed then, the part perimeter features are not recognized automatically in case there are no other features found by the system.
2.	CW-104667	CSR-15075	TechDB	In CAMWorks 2020 SP5, if a Mill-Turn machine is assigned as default machine in TechDB and then user proceeds to open a file in the CAMWorks user interface, an error message is displayed and then CAMWorks crashes.
3.	CW-104478	CSR-14972 CSR-14980	ShopFloor	When the published Shopfloor files are viewed in the respective application then, the relevant G-Code, Setup sheets and STL folders are not observed in the package.
4.	CW-104134	CSR-14761	TechDB	If a Mill-Turn machine is set as the default machine in TechDB and user proceeds to select a Mill machine in the CAMWorks application loaded as an Add-in within CAMWorks Solids, then CAMWorks Solids crashes.



CAMWorks 2020 SP5

Sr. No.	CPR Number	Help Desk ID	Area	Description
1.	CW-104216	CSR-14755	Toolpath	The leadin feedrate for Rough Mill operation with pattern type set to Volumill is always reset to Max feed rate value after closing and reopening the part file.
2.	CW-104215 CW-104214	CSR-14827 CSR-14800	Toolpath	The leadin feed rate for an Area Clearance operation with pattern type set to Volumill is output as Zero.
3.	CW-104171	CSR-14805	Toolpath	When the 3 Axis toolpath generation method is set to Advanced then, no toolpath is generated for Area Clearance operation with pattern type set to Adaptive
4.	CW-104089	CSR-14765	Post	Modify the APT post processor to include holder details along with the tool details.
5.	CW-104088	CSR-14731	Operation	When Save Operation Plan is done on a Multi Surface feature then, the leadin values defined for the 3 axis operations are not saved into TechDB.
6.	CW-104067	CSR-14646	TechDB	For the customized based TechDB, the user is unable to set default feature strategies as the data appears to be corrupted.
7.	CW-103899	CSR-14689	TechDB	In TechDB, the save option of the operation parameters is not enabled when the input option of the feed values are toggled between percentage and absolute modes.
8.	CW-103840	-----	UIF	When CAMWorks 2020 SP5 version is installed, then it is observed that the CAMWorks 2021 Utilities application, which was previously installed, does not get unloaded in the Add-in Page of CAMWorks application.
9.	CW-103771	CSR-14573	Machine Simulation	In CAMWorks Virtual Machine, when standard APT simulation is run then, the second front turret tools do not populate the turret.
10.	CW-103736	CSR-14575	TechDB	In TechDB, the user defined values for machining depth of operations for the curve features are not retained and instead they are reset to default values.
11.	CW-103732	CSR-14587	TechDB	In TechDB, for Tap cutting and Tap rolling tools, the column for the assigned stock material does not display material name instead displays list number associated to the stock.
12.	CW-103726	CSR-14585	Operation	The "Leadin Feedrate" value for 3 axis operations changes after a part is closed or reopened.



Sr. No.	CPR Number	Help Desk ID	Area	Description
13.	CW-103696	CSR-14475	Operation	When Feed/Speed is defined by tool and leadin feedrate applied to volumill toolpath is incorrectly set by the Z feedrate value of the tool.
14.	CW-103553	CSR-13796	TechDB	When the customized TechDB is used in CAMWorks then, the some of the toolpaths are not generated for the operations populated from by doing Generate Operation Plan.
15.	CW-103433	CSR-14367	License	CAMWorks License Manager needs to be modified to handle host id's string in the license request form that are too long for the license generator.
16.	CW-103430	CSR-14411	API	Api is required to change the SOLIDWORKS configuration.
17.	CW-103404	CSR-14409	Simulation	In Turn or Mill Turn mode the synchronized operations are incorrectly displayed in during step through simulation.
18.	CW-103403	CSR-14413 CSR-14430 CSR-14464	Operation	The leadin feed rates of Area Clearance operation with pattern type set to Volumill are always set to zero and user can change it only when the feed rate mode is set to percentage.
19.	CW-103385	CSR-14369	Operation	The modified values of lead in feed rate of 3 Axis operations are not retained when the operation parameter dialog is closed after accepting the modified values and reopened.
20.	CW-103305	CSR-14240	Post	The output for the post variables "WORK_PLANE_X_VEC_X", "WORK_PLANE_X_VEC_Y" and "WORK_PLANE_X_VEC_Z" is incorrect, when fixture coordinate system is not aligned to SOLIDWORKS coordinate system.
21.	CW-98655	CSR-12626	Toolpath	When the 3 Axis toolpath generation method is set to Advanced then, for the specific part, the toolpath for Area Clearance operation with pattern type set to Adaptive is not generated.
22.	CW-98231	CSR-12703 CSR-13367	Feature	When Thread Mill is applied for group hole features and the "Use skim plane" option and corresponding "Distance" value is applied, it doesn't update the toolpath skim retract between the features.
23.	CW-96659	CSR-11522	UIF	By default set the origin of the CAMWorks coordinate system to SOLIDWORKS origin. Currently the selection is left empty resulting in incorrect posted codes.



Sr. No.	CPR Number	Help Desk ID	Area	Description
24.	CW-92276	CSR-10552 CSR-10889	Rebuild	Switching between CAMWorks results in unnecessary rebuilds.
25.	CWR-1844 CWR-1843	CSR-13910	Toolpath	When the 3-axis toolpath generation method is set to "Advanced Method" then, for the specific part no toolpath is generated for Z Level operation.
26.	CWR-1840	CSR-13807	Toolpath	When the 3 Axis toolpath generation method is set to Advanced then, for the specific part incorrect toolpath is generated for Z level operation.



CAMWorks 2020 SP4

Sr. No.	CPR Number	Help Desk ID	Area	Description
1.	CW-103005	CSR-14184 CSR-14185 CSR-14186 CSR-14174 CSR-14250 CSR-14257 CSR-14263 CSR-14270 CSR-14272 CSR-14263	UIF	When SOLIDWORKS/CAMWorks application is closed then, an error message stating “ The operating system is not presently configured to run this application” is displayed.
2.	CW-102683	CSR-14139	Operation	For the specific part when the user tries to change the tool of the Constant Stepover operation then, a CAMWorks crashes.
3.	CW-102472	CSR-14093	Assembly	When the assembly file is launched in SOLIDWORKS with CAMWorks as an add-in then SOLIDWORKS crashes.
4.	CW-102418	-----	API	Add new API to set “Holder Type” from the available list of holder types in TechDB.
5.	CW-102377	CSR-14033	Post	The cutter compensation command of G 41/42 is found at incorrect location in the posted code of toolpath of Contour Mill operation.
6.	CW-102333	CSR-13967	UIF	The parameter of “Max link distance” is not visible on the links tab of Z Level operation parameters dialog box.
7.	CW-102142	CSR-13920	Operation	For an Assembly file, when a new operation is inserted interactively, then the new operation is listed under wrong setup.
8.	CW-102129	CSR-13795	Machine Simulation	In CAMWorks Virtual Machine, OKUMA P300 Controller the labels for “Work Coordinate fixture offset display”, “Length offset display”, “Diameter offset display” is incorrect.



Sr. No.	CPR Number	Help Desk ID	Area	Description
9.	CW-102128	CSR-13800	Machine Simulation	In CAMWorks Virtual Machine, OKUMA P300 Controller should support G30 Pxx; Individual sequence of axis moves.
10.	CW-102127	CSR-13816	Machine Simulation	In CAMWorks Virtual Machine with controller set to Okuma 300, an error message is seen while simulating the line having G86 command.
11.	CW-101924	CSR-13858 CSR-13898	UIF	When CAMWorks 2020 version is installed then, it is observed that the custom post processor files are deleted from the standard posts folder.
12.	CW-101688	CSR-13713	Translation	In Czech language version of CAMWorks, the translation of some of the labels in the "Continuous B axis settings" dialog box are incorrect.
13.	CW-101670	CSR-13700	Translation	In German language version of CAMWorks, the string "Probe operation" in CAMWorks command manager is incorrectly translated.
14.	CW-101618	CSR-13674	Toolpath	In Multi axis mill operation with pattern type set to Curve project, the user cannot edit the "Start hint" option.
15.	CW-101586	CSR-13663	Machine Simulation	In CAMWorks Virtual Machine, the Main spindle C-axis direction for sample Mill Turn machine is incorrect.
16.	CW-101585	CSR-13663	Machine Simulation	In Mill-Turn mode, if the first toolpath has B-axis milling moves then, the standard APT simulation using sample machine shows incorrect display.
17.	CW-101333	CSR-13574	Post	The values of "NEXT_OPR_TOOL" and "NEXT_OPR_SUB_STATION" are incorrectly set in the posted G code.
18.	CW-101272	CSR-13575	Post	For the specific assembly, incorrect sequence of operations is observed in the posted file which is generated from NC manager node.
19.	CW-101249	CSR-13540	System	The user is unable to restore the CAM data from assembly file when the customized TechDB is used.
20.	CW-101246	CSR-13549	Operation	For the specific part, when the parameter for Z level toolpath is changed then, CAMWorks crashes.



Sr. No.	CPR Number	Help Desk ID	Area	Description
21.	CW-101241	CSR-13547	Post	In assembly mode, when an operation having features combined in it and is also linked to another operation is post processed along with sub routines set to ON then, the posted G code doesn't contain the coordinates for all the features for which the tool path is generated. Instead the posted G code is generated for only one of the features.
22.	CW-101144	CSR-13505	Post	The value of length offset for probing operation is incorrectly output in the posted G code.
23.	CW-101126	CSR-13495	Toolpath	For the specific part, the toolpath of Turn finish operation with round insert is found to be gouging the part.
24.	CW-100877	CSR-13184	Machine Simulation	In CAMWorks Virtual Machine, the Rename shape dialog box is not translated in English language.
25.	CW-100865	CSR-13737	Operation	For the specific part CAMWorks error of unable to save CAMWorks entities is seen while closing the part.
26.	CW-100838	CSR-13384	Operation	For the specific part a crash in CAMWorks is seen when the user tries to edit the Thread Mill operation.
27.	CW-100829	CSR-13380	Operation	For the specific part, when "Edit Definition" is performed on some of the operations then, SOLIDWORKS crashes.
28.	CW-100282	CSR-13207	Toolpath	For the specific part the final pass of the contour mill toolpath is not generated when the depth processing is set as equal and ramp type is set to cut amount.
29.	CW-100248	CSR-13232	Toolpath	For the specific part the toolpath of Groove Finish operation gouges the part.
30.	CW-100186	CSR-13208	Toolpath	For the specific part the display of the automatic contain area profile is incorrect for the Z Level operation.
31.	CW-100006 CW-99103	CSR-13146 CSR-12745	Assembly	For the specific Assembly file, while switching from one configuration to another in the CAMWorks Feature tree, CAMWorks/SOLIDWORKS crash is observed.
32.	CW-99991	CSR-13126	Operation	When a Probe operation is preceded by a point to point operation then, in the posted G code the X, Y coordinates of the hole feature are not output in the Probe toolpath.



Sr. No.	CPR Number	Help Desk ID	Area	Description
33.	CW-99968	CSR-13124	Post	Unwanted moves are seen in the G code of a multi axis mill operation post processed using a post processor with "WORLD_POSITIONING=TRUE".
34.	CW-99796	CSR-13057	Operation	For a Mill-Turn part, when a Turn tool with station number greater than the last Mill tool in tool crib is added then, the newly added turn tool is displayed as Mill tool in tool preview.
35.	CW-99757	CSR-13090	Shop Floor	When a user defined Mill holder is used in CAMWorks, then, the same is not displayed in ShopFloor, in case if the holder is moved from it's current location.
36.	CW-99743	CSR-13070	Operation	For the specific assembly, the tool set for the entry drill operation is changed whenever the parent operation of Rough Mill is regenerated without any changes.
37.	CW-99583	CSR-13016	UIF	In German language version of CAMWorks, for the specific part, incorrect display of User Defined Turn Tool is seen.
38.	CW-99511	CSR-12989	Toolpath	For Contour Mill operations with chamfer machining set to ON, the display of the lead in/out moves is incorrect and is not as per posted code.
39.	CW-99458	CSR-12996	Translation	In Czech language version of CAMWorks, some of the labels are incorrectly translated in the scale dialog box of CAMWorks Additive Manufacturing.
40.	CW-99430	CSR-12966	Toolpath	For the specific part the toolpath of Rough Mill operation with pattern type set to Zigzag gouges the part.
41.	CW-99316	CSR-12897	UIF	In German language version of CAMWorks, the name of Bore operation is incorrectly translated.
42.	CW-99130	CSR-12870	UIF	In Czech language version of CAMWorks, the label "View system defaults" is not clearly visible in the Mill features tab of CAMWorks options dialog box.
43.	CW-99116	CSR-12845	License	When the user has purchased a 2.5 axis Mill license with Volumill 3axis then, the user is entitled to run rest machining for Volumill pattern.
44.	CW-99103	CSR-12745	Assembly	For the specific Assembly file, while switching from one configuration to another in the CAMWorks Feature tree, SOLIDWORKS crash is observed.



Sr. No.	CPR Number	Help Desk ID	Area	Description
45.	CW-98935	CSR-12820	Toolpath	For Contour Mill operation, the final finish pass feedrate is incorrectly applied to the final pass of the toolpath.
46.	CW-98845	CSR-12771	Translation	In Czech language version of CAMWorks, the parameters in the "Additional details" dialogue box for turn tool are not translated.
47.	CW-98506	CSR-12528	Toolpath	In Multi axis mill operation when, the leadin feed rate is modified then, the same feed rate is applied for the entire toolpath.
48.	CW-98421	CSR-12432	Feature	User cannot edit or modify the cut direction for vertical segments present in the curve feature.
49.	CW-98417	CSR-12494	Translation	In Spanish language version of CAMWorks, in TechDB under feature and operations of Hole feature, the sub type option of "Profundidad" should be renamed to "Ciego".
50.	CW-98203	CSR-12360	Toolpath	For the specific part, the toolpath generated for Rough Mill operation with contain area and pattern type set to Volumill gouges the island.
51.	CW-98074	CSR-12260	UIF	In Czech language version of CAMWorks, the labels "Deep groove cycle" and "Mirror about centerline" are aligned incorrectly in groove rough tab of operation parameters dialog box.
52.	CW-97682	CSR-12030	Post	Add the post variables "TOOL-ORIENT" and "TOOL_EDGE" in the post command "SETTOOLS".
53.	CW-97408	CSR-11908	Help	Information related to "Mirror" function needs to be added to the help file of Advanced tab of Mill part setup parameters.
54.	CW-97084	CSR-11751	Toolpath	If spiral entry is selected for Contour Mill operation on a circular pocket feature with CNC compensation set to ON and Toolpath center set to without compensation then, the display of the entry moves will be incorrect.
55.	CW-96933	CSR-11644 CSR-11707	Toolpath	Incorrect display is seen for the toolpath of Contour Mill operation with the options CNC compensation set to ON, Toolpath center set to without compensation and Gouge check set to True.



Sr. No.	CPR Number	Help Desk ID	Area	Description
56.	CW-94998	CSR-11055	Toolpath	For the specific part the display of toolpath for Contour Mill operation with CNC compensation set to ON and toolpath center set to without compensation is incorrect.
57.	CW-93553 CW-88018	CSR-10714 CSR-9593	Toolpath	When a Contour Mill toolpath is generated for multiple curve features then, the toolpath machining the first entity of the curve features does not contain XY feedrate.
58.	CW-89062 CW-84410 CW-95148	CSR-10052 CSR-7096 -----	Toolpath	The display of the toolpath of Entry drill operation generated for a Contour Mill toolpath with CNC compensation set to ON and toolpath center set to without compensation is incorrect.
59.	CW-88540	CSR-9750	Toolpath	For the specific part the toolpath generated for Area clearance operation with pattern type set to Volumill along with contain area gouges the part.
60.	CW-87829	CSR-9442	Toolpath	For the specific part the toolpath of Contour Mill toolpath generated on a hole feature gouges the part when the entry point is set to "Hole center".
61.	CW-87599	CSR-9261	Toolpath	For the specific part, the toolpath of Contour Mill operation on a part perimeter feature generates some unwanted passes.
62.	CW-87123	CSR-8929	Toolpath	For the specific part the toolpath of Rough Mill operation with pattern type set to Volumill and rest machining method set to From WIP or Previous left over along with a contain area generates passes which will be outside the profile of feature geometry.
63.	CW-77228	CSR-3667 CSR-3674 CSR-3107	Toolpath	For the specific part, the Contour Mill toolpath generated by rest machining on the Perimeter Boss feature has unnecessary spike moves at the open edge of the feature.
64.	CWR-1817	CSR-13461	Toolpath	For the specific part, when the 3 Axis toolpath generation method is set to "Advanced" then, the toolpath for Z level operation with depth method set to constant is incorrect.



Sr. No.	CPR Number	Help Desk ID	Area	Description
65.	CWR-1816	CSR-13424 CSR-13468	Toolpath	When the 3 Axis toolpath generation method is set to Advanced then, the toolpath for Pattern project operation with pattern set to Slice and XY stepover method set to "Scallop" doesn't generate passes to maintain constant scallop height all over the feature.
66.	CWR-1808	CSR-13342	Toolpath	When the 3 Axis toolpath generation method is set to "Advanced" then, for the specific part the toolpath for Flat area operation is not generated.
67.	CWR-1793	CSR-12753	Toolpath	When the 3 Axis toolpath generation method is set to "Advanced" then, for the specific part, the toolpath generated for Pattern project operation does not follow the user defined limit.
68.	CWR-1792	CSR-12753	Toolpath	When the 3 Axis toolpath generation method is set to "Advanced" then, the toolpath for Z level operation results in incorrect feed moves.
69.	CWR-1681	CSR-10948	Toolpath	When the 3 Axis toolpath generation method is set to "Advanced" then, for the specific assembly, the toolpath generated for Z level operation with corner type set to Round doesn't consider the max radius defined by the user. Instead sharp corners are generated in the toolpath.



CAMWorks 2020 SP3

Sr. No.	CPR Number	Help Desk ID	Area	Description
1.	CW-101208	CSR-13020	Feature	For the specific assembly incorrect depth is observed for the automatically recognized hole features. This happens when the "Extend holes to stock" is set to On.
2.	CW-100898	CSR-13195	Feature	A crash is seen in CAMWorks when the open profile feature is edited in the specific assembly.
3.	CW-100527	CSR-13321	Toolpath	When the toolpath of a thread mill operation with method set to Automatic is regenerated in CAMWorks 2020 then, an additional pass is created.
4.	CW-100417	CSR-13261	Machine Simulation	In CAMWorks Virtual Machine, when the controller type is set to Hass then, the X and Y positions of the additional coordinate system are incorrectly displayed.
5.	CW-100040	CSR-13160	TechDB	In TechDB, under Assembly tool crib the comment of Rolling tap is incorrectly displayed for Cutting tap.
6.	CW-100002	CSR-13128	Toolpath	For the specific Mill assembly, the toolpath generated for rough mill operation with pattern type set to offset roughing on an open pocket feature gouges the island.
7.	CW-99567	CSR-12959	TechDB	Unable to Update Stock Material Data from MES database with SQL Server.
8.	CW-99437	CSR-12707	Feature	In Mill assemblies when the option of "Extend holes to the stock" is set to true then, the recognized hole features are incorrectly extended in the opposite direction.
9.	CW-99355	CSR-12933	Post	If the Mill part setup has only Probing operations then, upon post processing the variable of "TLP_FEAT_SETUP_NAME" doesn't output the name of the Mill Part setup in the posted code.
10.	CW-99337	CSR-12937	Feature	User is unable to create a linear pattern of features by selecting edges along Z axis.
11.	CW-99191	CSR-12867	Operation	When a tool is copied in the tool tree tab then the operations associated with it are also copied along with the tool.
12.	CW-98844	CSR-12770	Translation	In Czech language version of CAMWorks, the labels "Insert ID" and "Holder ID" of Turn tool assemblies is translated incorrectly in TechDB.



Sr. No.	CPR Number	Help Desk ID	Area	Description
13.	CW-98794	CSR-12740	Operation	For the specific part a crash is seen in CAMWorks when generate toolpath is done on a contour mill having an avoid area.
14.	CW-98699	CSR-12665	Machine Simulation	When the active license doesn't include a 5 axis module then, incorrect display is seen in CAMWorks Virtual Machine if the rotary axis angle of a setup is manually overridden.
15.	CW-98659	CSR-12620	Feature	For the specific part significant time is taken to create a circular pocket interactively.
16.	CW-98533	CSR-12599	TechDB	In TechDB user cannot set the value of more than 90 degrees for all the leadin/leadout angles of the Turn operations.
17.	CW-98525	CSR-12342	TechDB	Whenever a mill tool is copied and, the diameter of the new tool is modified then, the value set for cutting speed (SMM/SFM) is not automatically updated as per the new value of diameter.
18.	CW-98507	CSR-12515	Toolpath	For the specific assembly, when fixtures are defined in the Mill Part Setup then, the toolpath for Contour Mill operation with bottom finish set to On is incorrectly generated.
19.	CW-98491	CSR-12465	API	When a 5 axis mill machine selected by using an API is edited in the CAMWorks operation tree then, an error message is displayed.
20.	CW-98434	CSR-12514	TechDB	For a customized TechDB, the user is unable to add operation parameters for a default Probe operation.
21.	CW-98387	CSR-12482	Post	In Mill Turn, for operations of face setups the value set for "Maximum Arc Deviation" is incorrectly output.
22.	CW-98357	CSR-12421	Post	For the specific Mill part, in Multiaxis Mill operation, when the value of "Angle tolerance" under "Pole handling" is set to 10 degrees then, CAMWorks crashes when the operation is post processed.
23.	CW-98321	CSR-12461	Post	The value of "IS_PATTERN_FEATURE" is always set to 0 when, the toolpath for the pattern of an automatically recognized feature. However, the value is set to 1 in case if the feature is interactively inserted.



Sr. No.	CPR Number	Help Desk ID	Area	Description
24.	CW-98294	CSR-12386	TechDB	For taper End Mill tools, when the cutting speed (SMM) value is modified then, the values calculated for RPM and other feedrates are incorrect.
25.	CW-98209	CSR-12362	System	For the specific assembly file, when the user enables or disables instances in the Active Instances dialog box then SOLIDWorks crashes.
26.	CW-98167	CSR-12299	Translation	In German language version of CAMWorks, the string "Probing" is incorrectly translated.
27.	CW-98164	CSR-12182	System	For the specific part, after sorting the operations the user is unable to save the part file and all the CAM data is lost.
28.	CW-98114	CSR-12296	Feature	For a Wrap feature when Fixture Coordinate system is changed then error message stating "Unable to generate toolpath for wrapped feature" is displayed.
29.	CW-98108 CW-97109 CW-95149	CSR-12295 CSR-11733 Beta	Toolpath	The leadin/out points defined for a Contour Mill operation cannot be edited if the operation machines multiple curve features with chamfer machining option set to On.
30.	CW-98079	CSR-12269	Simulation	For the specific part an error is seen while simulating the multi axis toolpath.
31.	CW-98074	CSR-12260	UIF	In Czech language version of CAMWorks, the labels "Deep groove cycle" and "Mirror about centerline" are aligned incorrectly in groove rough tab of operation parameters dialog box.
32.	CW-98073	CSR-12259	Translation	In Czech language version of CAMWorks, the strings "Covert to face feature" and "Convert to cutoff feature" are incorrectly translated.
33.	CW-98028	CSR-12178	TechDB	In TechDB the user is unable to set User Defined Turn Insert for threading operations.
34.	CW-97921	CSR-12132	API	Add an API to create a common list of tools by browsing through all available CAMWorks configuration in the part/assembly.
35.	CW-97774	CSR-12095	Feature	For the Assembly file, when "Rebuild" is performed then SOLIDWorks crashes.



Sr. No.	CPR Number	Help Desk ID	Area	Description
36.	CW-97683	CSR-12043	Machine Simulation	In CAMWorks Virtual Machine, the spindle rotation is not seen if the commands of M03 and G234 are in the same line.
37.	CW-97582	CSR-11945	Translation	In Spanish language version of CAMWorks, the string "Tab cutting" is incorrectly translated in the Contour Mill tab of operation parameters dialog box.
38.	CW-97576	CSR-11945	UIF	In Spanish language version of CAMWorks, the spin controls for the depth parameters function incorrectly when the check box of tab cutting is selected.
39.	CW-97134 CW-95246	CSR-11800 CSR-9094	Simulation	For the specific part the display of the coordinate system is incorrect during toolpath simulation. However, it is properly displayed during step through.
40.	CW-96980	CSR-1702	Operation	The toolpath generated for Drill operation on a group of Counter Bore hole features is incorrect as the user defined start and end point are considered only for the first instance and not for all other instances.
41.	CW-96032	CSR-11315	TechDB	In TechDB the column width of Machines, Strategies and Tool cribs should be made equal.
42.	CW-95998	CSR-11187	Operation	When the parameters of an operation having multiple features in it are updated (By doing Generated Operation Plan) then, the machining depth for all the features is reset to a common value.
43.	CW-94482	CSR-10901	TechDB	In Czech language version of CAMWorks, the strings "Use chamfer machining" and "Geometry condition" is incorrectly translated in the Contour tab of operation parameters dialog box.
44.	CW-94193	CSR-10852	Operation	In mill assembly mode, if the SOLIDWORKS coordinate system used to define origin of a Mill Part Setup is renamed then, the origin is not updated with the new name.
45.	CW-94111	CSR-10797	Simulation	For the specific part an error is seen while simulating the Rough toolpath.
46.	CW-93581	CSR-10638 CSR-11271	Toolpath	The incorrect display of the toolpath is observed for Contour Mill operation with CNC compensation set to On and Toolpath center to without compensation.



Sr. No.	CPR Number	Help Desk ID	Area	Description
47.	CW-91918	CSR-10426	Toolpath	For the specific part, the toolpath generated for a Contour Mill operation with bottom finish set to On and high-speed parameters gouges the part.
48.	CW-88664	CSR-9782	API	Develop an API to list the operations and the associated features.
49.	CW-88201	CSR-9279 CSR-10728	Operation	The coolant type set in TechDB for a mill tool is not reflected in CAMWorks if the same tool is used as part of an assembly tool.
50.	CW-85711	CSR-8027	TechDB	In Mill operations if the Feeds and Speeds are defined by the tool then, the leadin feedrate is incorrectly set by the Z feedrate of the tool.
51.	CW-84528	CSR-7143	Toolpath	For a Contour Mill toolpath generated for a closed feature with Contain area, if the CNC Compensation is changed to 'Off' and Toolpath Centre to 'Without Compensation', then it results in the toolpath not changing position as expected like the G code coordinate.
52.	CW-84212	CSR-6946	Translation	In Japanese language version of CAMWorks, the strings for operation parameters are incorrectly translated.
53.	CWR-1798	CSR-12904	Toolpath	When the 3 axis toolpath generation method is set to "Advanced Method" then, the toolpath for Pencil Mill operation generates incorrect leadin/leadout move, when the holder avoidance option is enabled.
54.	CWR-1790	CSR-12668	Toolpath	For the specific Mill Part, no toolpath is generated for Pencil Mill operations with the holder avoidance option set to True.
55.	CWR-1789	CSR-12669	Toolpath	When the 3 Axis toolpath generation method is set to "Advanced" then, no toolpath is generated for the Area Clearance operation with Holder Avoidance set to True.
56.	CWR-1772	CSR-12166	Toolpath	When the 3 axis toolpath generation method is set to "Advanced Method" then, for the specific part the rapid moves of the Z Level operation gouge the part.
57.	CWR-1693	CSR-7282	Toolpath	When the 3 Axis toolpath generation method is set to "Advanced" then, for the specific part some of the passes are not generated for the Z level operation with depth method set to "Scallop".



CAMWorks 2020 SP2

Sr. No.	CPR Number	Help Desk ID	Area	Description
1.	CW-99518	CSR-13005	Translation	In German language version of CAMWorks, the command names in the CAMWorks NC Editor tab are incorrectly translated and interchanged.
2.	CW-99135	CSR-12846 CSR-12789	Operation	In Turn mode, the functionality to automatically set the spindle rotation direction(CW/CCW) based on hand of cut, feature being machined, and spindle being used is functioning incorrectly and needs to be improved.
3.	CW-97602	CSR-11981	Feature	For the specific part, incorrect hole features are recognized when features are recognized after creating a Mill Part Setup.
4.	CW-97372	CSR-11876	Operation	When Generate Operation Plan is selected after inserting new features then, the parameters of earlier created operations are changed along with the creation of new operations from TechDB. Under such circumstances only operations for new features should be created and existing operations shouldn't be affected.
5.	CWR-1781	CSR-12368	Toolpath	For the specific Mill Part model, the Area Clearance Toolpath that peruses Mirror function fails to generate when the Toolpath Generation Method is set to 'Advanced'. An internal error message is displayed.
6.	CWR-1771	CSR-12062	Toolpath	When the 3 axis toolpath generation method is set to Advanced then, incorrect toolpath generated for Z-level operation with negative XY allowance.
7.	CWR-1767	CSR-11883	Toolpath	When the 3 axis toolpath generation method is set to Advanced then, for the specific Mill part, no toolpath is generated for Area Clearance operation if the depth parameter is set to Scallop and the option of hit flats is set to On.
8.	CWR-1765	CSR-11886	Toolpath	When the 3 axis toolpath generation method is set to Advanced then, for the specific Mill part, it is observed that the toolpath for Z level operation skips one of the Z level.
9.	CWR-1764	CSR-11885	Toolpath	When the 3 axis toolpath generation method is set to Advanced then, the toolpath of Area Clearance operation with "Adaptive Stepdown" and "Hit Flats" set to ON doesn't machine the flat areas in the feature.
10.	CWR-1682	CSR-10980	Toolpath	When the 3 Axis Toolpath Generation method is set to Advanced then, for the specific part, the toolpath for Z level operation results in feed move that violates ramp angle and results in tool breakage.



CAMWorks 2020 SP1

Sr. No.	CPR Number	Help Desk ID	Area	Description
1.	CW-98107	CSR-12286	Toolpath	For the specific Mill part, when spring passes are applied to Thread Mill operation, then extra spring passes are generated in the Z direction with wrong depth.
2.	CW-97884	CSR-12157	Toolpath	With the specific part, a crash is seen in SOLIDWORKS/CAMWorks Solids when a Rough Mill toolpath with pattern type set to "Zig" and tool type set to tapered ball nose is generated with on a Rectangular Pocket feature.
3.	CW-97712	CSR-10156 CSR-11158 CSR-8316	Toolpath	The toolpaths generated for Thread Mill operations with Conventional Milling and thread passes are incorrect. For all spring passes from the second one onwards, the toolpaths are offset in Z direction by a thread pitch.
4.	CW-97684	CSR-10156 CSR-11158 CSR-8316	Toolpath	The toolpaths generated for Thread Mill operations when Leadin/Leadout Method is set to 'Auto', the leadin and leadout generated for all passes from second pass onwards are incorrect. No linear feed moves are observed before and after arcs for Cutter Compensation are observed for these passes.
5.	CW-97496	CSR-11940	TechDB	In SQLite-based TechDB, for Roughing operations, the user is unable to modify the "Auto Correct" option for Entry Points in the Feature Options tab of Operations interface.
6.	CW-97495	CSR-11916	Toolpath	The cut direction of climb/conventional in a toolpath for Contour Mill operation on a curve feature is controlled by the order in which the segments have been selected. But, the cut direction should be independent of the selection order.
7.	CW-97403	CSR-11873 CSR-11929	TechDB	When TechDB of CAMWorks 2019 is imported into CAMWorks 2020 then, the values of parameters associated with Probe operation are incorrectly imported.
8.	CW-97370	CSR-11862	Translation	In Czech language version of CAMWorks, the translation of the units for the parameters 'Back Angle>' and 'Back Angle<=' in TechDB should be 'Degrees' instead of 'mm'.
9.	CW-97315	CSR-11836	Translation	In Czech language version of CAMWorks, the translation for the names of the Mill Face feature, Turn Face feature and some of the Mill tools in TechDB is incorrect.
10.	CW-97058	CSR-11671	UIF	For the specific Turn Part, the display of the Turn tool holder is incorrect during step through and simulation.



Sr. No.	CPR Number	Help Desk ID	Area	Description
11.	CW-97050 CW-87834	CSR-11741 CSR-9454	Toolpath	The toolpaths generated for Rough Mill operations with pattern type set to Volumill shift away from the feature location when the machining depth is overridden by the user.
12.	CW-97032	CSR-11717	Post	Correction required in NC code generated using Mill-Turn post processors. When doing X Plus only on Face Fixed in Mill-Turn mode, if SPINDLE_ORIENTATION = 0, then don't call CALC_OUTPUT_POLAR_SPINDLE_ORIENTATION.
13.	CW-97028	CSR-11714	Assembly	For the specific Assembly file, while switching from one configuration to another in the CAMWorks Feature tree, SOLIDWORKS crash is observed.
14.	CW-96999	CSR-11693	Translation	In Czech language version of CAMWorks, the names of some of the parameters associated with the Probing Operation interface need to be modified as they are incorrect.
15.	CW-96945	45627	Help	In the Help documentation for post variables associated with Probing functionality, the names of some of the the variables are incorrect. The variables "probe_j_cycle_spec_dist_x" and "probe_k_cycle_spec_dist_x" need to be renamed to "probe_j_cycle_spec_dist_y" and "probe_k_cycle_spec_dist_z" respectively.
16.	CW-96944	CSR-11661	System	In the set up tab of Machine dialog box, when indexing limit is changed then the option "Update indexing angles for setups" updates angles of the existing Mill Part setup but, the orientation remains same.
17.	CW-96913	CSR-11611	Post	Do not allow posting of Probing operations if the post processor has the header of "If ALLOW_PROBING" set to false.
18.	CW-96624	CSR-11187	Operation	For specific mill parts, when rebuild is performed then, the machining depth of the Countersink operations for hole feature gets modified.
19.	CW-96594	CSR-11481	UIF	If user manually selects multiple operations in the Operations tree with the last operation selected being a probe operation, then the Post Process command is not available in the context menu.
20.	CW-96588	CSR-11476	Toolpath	For the specific part the retract move of the Turn Drill operation gouges the part.
21.	CW-96586	-----	Machine Simulation	In CAMWorks Virtual Machine, the gang tools are displayed incorrectly.
22.	CW-96567	CSR-11465	Simulation	In simulation the thread mill tool assigned to a thread mill operation is displayed incorrectly.



Sr. No.	CPR Number	Help Desk ID	Area	Description
23.	CW-96537	CSR-10716	Machine Simulation	In CAMWorks Virtual Machine with controller type set to Siemens, the depth simulated for drill operations is incorrect.
24.	CW-96376	CSR-11400	System	For the specific Mill Assembly user is unable to switch between configurations and retain the features and operations of the active configuration.
25.	CW-96295	CSR-11371	Machine Simulation	Simulation of Probing cycles must be supported on CAMWorks Virtual Machine.
26.	CW-96266	-----	API	Add new APIs to Set/Get Methods for all Turn Tool and Holder parameters also develop a macro for Turn Tooling.
27.	CW-96027	CSR-11316	UIF	When the stock for any Mill part is defined using a sketch, it is observed that length of the stock in X direction will always be the biggest number from the lengths defined in the three directions instead of following lengths as per the defined Coordinate System.
28.	CW-95997	CSR-11323	ShopFloor	In CAMWorks Shopfloor, the toolpaths are not visible even though the display option of OpenGL display is set to 'Hidden line'.
29.	CW-95995	CSR-11317	Toolpath	For the specific Mill assembly, the toolpath generated for rough mill operation with pattern type set to Volumill on an open pocket feature gouges the island.
30.	CW-95812 CW-95809	CSR-10773	TechDB	When a customized TechDB is used in conjunction with CAMWorks and a tool is added from the TechDB to the Tool tree then, incorrect values are populated for Tool ID, Tool material and Coolant type.
31.	CW-95491	CSR-11138	TechDB	When user attempts to define a Taper tool in the TechDB, the application doesn't allow the End Diameter (D1) of the tool to be less than the Shoulder Diameter value (D4).
32.	CW-95248	CSR-11008	VoluMill	When Rough Mill toolpath [with VoluMill pattern and Entry Method set to 'Pre-drilled Holes' in VoluMill Settings dialog box] is generated for grouped pocket features, then it is observed that the toolpath doesn't follow the entity at the entry points. However, VoluMill toolpath generates correctly if applied to individual pocket features.
33.	CW-95177	CSR-11098	Machine Simulation	Incorrect "Shoulder Diameter" value is passed from TechDB to CAMWorks Virtual Machine application.
34.	CW-95176	CSR-11060 CSR-11108	UIF	User must select the thread type and size twice in order to associate it with the active hole feature. It should be possible to set the required thread type with only one attempt.



Sr. No.	CPR Number	Help Desk ID	Area	Description
35.	CW-95172	44924	Translation	In Polish version of CAMWorks, the translation of the parameter "Effect Lead Angle" in Continuous B axis user interface is incorrect.
36.	CW-95145	44893	Feature	The number and location of the tabs set in a contour mill operation are not updated correctly when the feature is modified and CAMWorks data is rebuilt.
37.	CW-95113	44868	Translation	The translation for many of the parameters present in NC tab of Turn Operation Parameters dialog box is incorrect.
38.	CW-95005	CSR-11073	Toolpath	In rough mill operations with pattern type set to Volumill, an extra pass is generated if the machining depth of the feature is increased.
39.	CW-94893	CSR-11035	Post	Add two new post variables for passing info on 4th and 5th axis reverse directions (i.e. whether the Rotary and Tilt axis reverse checkbox in the Machine dialog box is checked or not).
40.	CW-94631	44963	Translation	In Polish language version of CAMWorks, the translation for "Part bounding Box Vertex" and "Stock Bounding Box Vertex" in Fixture coordinate system tab is incomplete.
41.	CW-94493	CSR-10888	Toolpath	In Area Clearance operations with pattern type set to Volumill, the user defined entry points are ignored.
42.	CW-93610	CSR-10731	TechDB	For the specific customized TechDB, the hole thread mapping table displays empty fields for the parameters. This results in incorrect mapping of hole features in CAMWorks.
43.	CW-93578	CSR-10706	TechDB	When a tool is added in the Assembly tool crib with the "Combination ID" filter then, the first tool from the overall assembly list is selected instead of the first tool in the list of filtered tools.
44.	CW-93544	CSR-10684	TechDB	In Tooling section of TechDB, for drill tools, the Shoulder diameter value is not editable under 'Straight' shank. It remains unchanged when the 'D1' value is modified. Although this parameter is disabled, it must still display the correct updated value within its corresponding field.
45.	CW-93234	CSR-10635	Toolpath	While machining MS Hole features with rough mill operation with pattern type set to Volumill, a portion of the toolpath is deleted if a negative bottom allowance is given or if the machining depth is increased.
46.	CW-93073	CSR-10631	Translation	In French version of CAMWorks, for Turn/ Mill-Turn mode, the translation of Main Spindle and Sub Spindle options for Spindle Origin parameter in Origin tab of Operation Setup Parameters dialog box is incorrect.



Sr. No.	CPR Number	Help Desk ID	Area	Description
47.	CW-92825 CW-83439	CSR-10562 CSR-6311	UIF	For dual-screen setups, the Operation Parameters dialog box for Multiaxis Mill operations opens up only on the first screen unlike other Mill operations that open at the last screen position.
48.	CW-92760	CSR-10589	Simulation	For the specific Turn part model, when Simulation is run at low speeds (less than 30%), a warning message indicating collision between tool holder and stock is displayed. However, if Simulation is run at full speed (100%), then no warning message about collision is observed.
49.	CW-92593	CSR-10578	Operation	The values assigned as additional amount for leadin/out moves of Contour Mill operation in TechDB do not make any impact on the generated toolpath until the operation is edited and the toolpath is regenerated.
50.	CW-92182	CSR-10479	Toolpath	For the specific part the incorrect toolpath is generated for Rough Mill operation with pattern type set to Volumill and rest machining method is set to WIP.
51.	CW-91965	CSR-10461	Simulation	For the specific part model, when user attempts to run Simulation at full speed, an error message regarding inability to run simulation is displayed. However, if user reduces the Simulation speed to any speed less than 100%, then simulation runs successfully without any hitch.
52.	CW-90583	CSR-10243	UIF	When multi-screen/ dual-screen setup, depending on the definition of which screen/monitor is assigned as the Main screen, CAMWorks dialog boxes may or may not open at the last screen position. In some cases, the dialog boxes end up opening in a non-visible location leading to confusion.
53.	CW-89986	CSR-10156 CSR-11158	Toolpath	In Thread milling operation on a hole feature with multiple passes the leadin move is observed only on the first pass and not on other passes.
54.	CW-89002 CW-85343	CSR-10028 CSR-10035 CSR-10923 CSR-9832 CSR-7483	Toolpath	The NC code for VoluMill operations that were generated for Wrapped features on Mill-Turn part models output incorrect moves. Arc moves are posted as line moves.
55.	CW-89001	CSR-10021	Simulation	For the specific Mill part model with Multiaxis Mill toolpaths, error message is displayed when user attempts to run simulation.
56.	CW-88983	CSR-9973	Operation	In Mill mode, when 'Sort Operations' is done then, multiple Mill Part Setups with identical names are created.
57.	CW-88685 CW-86727	CSR-10857 CSR-9836 CSR-8742	Simulation	The display of the User Defined Drill tools in simulation is incorrect.



Sr. No.	CPR Number	Help Desk ID	Area	Description
58.	CW-88654	CSR-9895	Toolpath	For the specific Mill part, the Contour Mill toolpath generated for an Open Profile feature (with Avoid Area defined along the feature boundary) gouges the part.
59.	CW-88621	CSR-9833	Post	For Mill-Turn part models, if the Contour Mill operations generated for its Counterbore holes are machined using Turn tools in the Front turret, then it is observed that Arc moves are posted incorrectly in the NC code.
60.	CW-88576	CSR-9836	UIF	For the specific Turn part, the display of the User Defined Turn inserts is incorrect in step through simulation.
61.	CW-88542	CSR-9821	VoluMill	For the specific Mill part model, a 2.5 Axis VoluMill toolpath has been generated for an irregular slot feature. It's observed that this toolpath gauges the part on the slot feature as it creates a wrong feed link in the air segment portion of the slot feature. No gouging by toolpath is observed when Rough Mill patterns other than VoluMill are used.
62.	CW-87702	CSR-9385	UIF	In turn mode, when the chuck display is set to ON then, the display of the part during rotation is not smooth.
63.	CW-87376	CSR-9072	Translation	In Czech language version of CAMWorks, the parameter "Depth>" is incorrectly translated in tap cutting and tap rolling menu of TechDB.
64.	CW-87312	CSR-9031	Operation	In Mill Assembly mode, if the fixture components are selected by window selection then, even the hidden components are added as fixtures.
65.	CW-86727	CSR-8742	Simulation	The profile of the User Defined Tool set for a drill operation in Turn mode is incorrectly displayed during simulation.
66.	CW-86265	CSR-8289	Feature	If a hole group feature is simulated after reducing the number of holes within the hole group features, then each existing hole feature is drilled twice. This happens because the deleted hole features are added twice with the next hole in the hole group.
67.	CW-86260	CSR-8316	Toolpath	Cutter comp is not cancelled properly when the leadout for thread mill is set to Automatic. While using the Automatic Leadout option for Thread mill, the toolpath should include a linear feed move from the end of the arc leadout to the center of the hole for cut comp to be cancelled properly.
68.	CW-86057	CSR-8258	Assembly	For the specific Assembly file, when user attempts to edit the Tool Crib associated with its second machine, SOLIDWORKS crashes.
69.	CW-86030	CSR-8224	Feature	When defining a Mill part setup in assembly, the user is unable to select an assembly level plane from the SOLIDWORKS feature manager.



Sr. No.	CPR Number	Help Desk ID	Area	Description
70.	CW-85898	CSR-8096	TechDB	With custom TechDB, the corner radius value for a Flat End mill is considered while displaying the shape of the tool during simulation. This makes the display of the tool incorrect.
71.	CW-85343	CSR-7483	Toolpath	In Mill-Turn mode, when VoluMill toolpaths are generated for OD Wrap features, it is observed that the toolpaths contain arc moves. This is incorrect as Arc moves aren't supported for OD Wrap features when post processing. Consequently, posted NC code ends up generating linear moves to connect arc end points, thereby resulting in incorrect toolpaths.
72.	CW-83769	CSR-6558	Simulation	For the specific Mill part, the geometry of the Dovetail tool assigned to its Contour Mill operation is incorrectly displayed during simulation.
73.	CW-81150 CW-74885	CSR-11580 CSR-6717 CSR-5350 CSR-5209 CSR-2768	Machine Simulation	For specific Mill Assembly FILES, data associated with stock is not displayed when running standard Machine Simulation using CAMWorks Virtual Machine. This occurs as stock related data is not passed on to the CAMWorks Virtual Machine application.
74.	CW-79706	CSR-4725	UIF	The display of the Trigonal insert mounted on Front Turret is incorrect when it is accessed from tools tree. The same incorrect display is shown in CAMWorks Virtual Machine.
75.	CW-78124	CSR-4029	Stock	A functionality needs to be provided whereby users can define the quality and deviation of the stock while using SOLIDWORKS stock (part file/ assembly). Currently, this functionality is available only for STL-based stocks.
76.	CW-77438	CSR-3772	TechDB	When using customized TechDB, if the Generate Operation Plan command is executed for Threaded Hole features, inactive tap- cutting/ tap-rolling tools get assigned to the generated operations along with active ones. CAMWorks doesn't filter out inactive tap tools before tool allocation.
77.	CW-74918	CSR-2783	VoluMill	For the specific Mill part model, the VoluMill toolpath fails to generate when the Feature Depth in Feature Options tab is overridden or when the Origin is set to below the feature in Z direction in Origin tab.
78.	CW-74885	CSR-2768 CSR-5350 CSR-6717	Machine Simulation	when standard APT machine simulation is run for a specific assembly, it is observed that stock related data is not passed on to CAMWorks Virtual Machine.
79.	CW-70633	CSR-899	Toolpath	The Volumill toolpath generated on a wrapped feature is incorrectly post processed as the circular moves are not split into linear moves. This results in erroneous machining of the feature.



Sr. No.	CPR Number	Help Desk ID	Area	Description
80.	CW-70268	CSR-663	Toolpath	For the specific part, incorrect toolpath is generated for Rough Mill operation with pattern type set to Volumill when the step over percentage set between 9.99 and 10.01%.
81.	CWR-1726	CSR-11512	Toolpath	When the 3 Axis Toolpath Generation method is set to Advanced then, for the specific part an error is observed in the posted output of the toolpath of Area Clearance operation. The error is due to incorrect computation of arcs.
82.	CWR-1724	CSR-11436	Toolpath	When the 3 Axis Toolpath Generation method is set to Advanced then, for the specific part the toolpath for Z Level operation is not generated because of incorrect computation of avoid surfaces.
83.	CWR-1687	CSR-11111	Toolpath	When the 3 Axis Toolpath Generation method is set to Advanced then, for the specific part the toolpath for Z Level operation with contain area defined using multiple closed loops is not generated.
84.	CWR-1685	CSR-10955	Toolpath	When the 3 Axis Toolpath Generation method is set to Advanced then, for the specific part the entry moves with entry type set to spiral for an area clearance operation are incorrect as the tool is made to cut the material in both directions.
85.	CWR-1675	CSR-10894	Toolpath	When the 3 Axis Toolpath Generation method is set to Advanced then, for the specific Mill part uneven cut depth is observed for Z Level toolpath.
86.	CWR-1674	CSR-10816	Toolpath	When the 3 Axis Toolpath Generation method is set to Advanced then, for the specific Mill part high amount of time is taken to compute the toolpath for Z Level operation with Max Link distance set to 20mm.
87.	CWR-1672	CSR-10785	Toolpath	When the 3 Axis Toolpath Generation method is set to Advanced then, for the specific assembly, the Area Clearance Toolpath is not maintaining the user defined allowance.
88.	CWR-1665	CSR-10506	Toolpath	When the 3 Axis Toolpath Generation method is set to Advanced then, for the specific part the toolpath for Pattern Project operation with Mach Deviation set to 0.0001 us bit generated.



CAMWorks 2020 SP0

Sr. No.	CPR Number	Help Desk ID	Area	Description
1.	CW-96721	CSR-11576	UIF	In Wire EDM module, the insert new feature command in CAMWorks command manager is incorrectly displayed as "Mill feature".
2.	CW-96658	CSR-11435	Operation	User is not able to select a User Defined Turn tool for any turning operations although the tool is properly defined in TechDB.
3.	CW-96567	CSR-11465	Simulation	While simulating Thread Mill operations, incorrect display of the thread mill tool seen in case if an ineffective length is defined for the tool.
4.	CW-96622	CSR-11491	Operation	For a Turn part, the user set strategy of 'Thread' is not retained and is reset to a default strategy when the same feature is edited again.
5.	CW-96275	CSR-11374	Post	When probe operations are posted using a post processor which doesn't support probe operations then, an error message should be displayed.
6.	CW-96206	CSR-11332	Help	Add "UPDATE_WORK_OFFSETS_CYCLE" as a constant instead of variable in Universal Post Generator help file.
7.	CW-96205	CSR-11347	Toolpath	The toolpath for probe operation is not generated automatically when the Work coordinate system is modified in the operation parameters.
8.	CW-95999	CSR-10728	Operations	With the customized TechDB, the coolant information for an assembly tool is incorrectly displayed in CAMWorks.
9.	CW-95218	Beta - 44916	Translation	In Polish language version of CAMWorks, the labels for the probing parameters needs to be modified.
10.	CW-95127	44955	Translation	In Polish language version of CAMWorks, the text "Chamfer for curve feature" is incorrectly translated in the Options dialog box.
11.	CW-95126	Beta-44867	UIF	The values of "Thread Depth" and "Pitch" in the OD profile parameters dialog box cannot be modified by user even though the parameters are active.
12.	CW-94495	-----	Translation	In Spanish language version of CAMWorks, the text of "Auto Select Edges For Chamfering" is incorrectly translated in the 2.5 axis feature select entities dialog box.



Sr. No.	CPR Number	Help Desk ID	Area	Description
13.	CW-94441	CSR-10920	Operation	When the machining depth of the counterbore hole feature is modified by changing the Hole start and end offset, the same is not reflected in the machining depth on the feature options tab of the operation.
14.	CW-94155	Beta-44226	Post	The Work Coordinate System details from the probe operation are incorrectly output in case the probe operation happens to be at the start of the Mill Part Setup.
15.	CW-94089	CSR-10792	Feature	For the specific part, when a rectangular slot feature is defined using a sketch then, the direction of the profile segment is incorrectly displayed.
16.	CW-93584	-----	UIF	In a Probe operation tab, allow the user to modify the default depth in Z axis by activating the offset parameter.
17.	CW-93247	CSR-10695	Setup Sheet	The setup sheet generated for Turn Operation displays the spindle speed in terms of SMM even though the same has been defined in terms of RPM.
18.	CW-92747	CSR-10600	Post	In Universal Post Generator-2, it is observed that "F5" shortcut option which is used for compiling post window is missing in file menu.
19.	CW-92266	CSR-10532	Feature	For the specific part, the curve feature profile "Flip direction to cut" doesn't get updated while performing the Edit feature function after saving it. The flip direction to cut of the feature profile is returned to the previous condition.
20.	CW-92231	CSR-10457	Post	Add the ability in the post processor to know about the indexing details of the selected machine.
21.	CW-92161 CW-88653	CSR-10428 CSR-9880	Simulation	For the specific parts incorrect display of tap tool is seen during simulation of tapping operations.
22.	CW-91645	CSR-10328	Assembly	For the specific Assembly file, when the CAMWorks configurations are changed in the CAMWorks NC Manager then, CAMWorks crashes.
23.	CW-91143	CSR-10333	API	In the assembly mode, when the macro to change the machine type is executed then SOLIDWORKS crashes.
24.	CW-90978	CSR-10306	System	In Turn and Mill-Turn mode, the user will not be able to assign feeds and speeds to any operations using tools from the second Rear or Front turrets. Because of such a limitation, the user will not be able to generate any toolpaths.



Sr. No.	CPR Number	Help Desk ID	Area	Description
25.	CW-90581	CSR-10232	Toolpath	When a toolpath is edited and if some of the segments are deleted then, the newly created links do not adhere to the value of "Auto safe Z plane" and are created at rapid plane location.
26.	CW-90155	CSR-10190	ShopFloor	To have a version of CW Shopfloor in Czech language.
27.	CW-88697	CSR-9903	Help	Add description regarding variable of "PRT_PATH" in Universal Post Generator help document.
28.	CW-88394	CSR-9948	Operation	The direction of tabs in contour mill operations for part perimeter feature is incorrect.
29.	CW-88257	CSR-9684	Post	The Z co-ordinates of a Multi axis mill operation on a sub spindle setup in a Mill-Turn machine should be referenced from the sub spindle co-ordinate system and not the main spindle co-ordinate system.
30.	CW-87825	CSR-9452	Translation	In Japanese language version of CAMWorks, the string "Canned Cycle" is incorrectly translated.
31.	CW-87537	-----	Feature	For the specific part, when "Extract Machinable Feature" command is executed then the features are not generated.
32.	CW-87407	CSR-9113	Toolpath	For Multi Axis Mill operations with the method set to Swarf Milling, the method of 'Sorting' is disabled when the number of cuts in stepover pattern is set to 1.
33.	CW-87281	CSR-9009	TechDB	In Mill Tooling>>Threading menu, the spindle type defined for "Tap Cutting" and "Turn Tap Operations" is different. Due to this, operations are not generated when Generate Operation Plan is done.
34.	CW-87128	CSR-8908	Operation	The "Start code" and "End code" fields in wait code settings dialog box of CAMWorks Sync Manager, should not accept negative values.
35.	CW-86874	CSR-8812	Feature	Islands are not recognized on slot feature when the "Recognize feature by depth" option is enabled in the Mill Features tab of Options dialog box.
36.	CW-86503	CSR-8567	Feature	In Mill-Turn, user cannot select an edge of the part to define the axis to create a pattern for a feature.
37.	CW-85730	CSR-8015	API	Incorrect values are being returned with "ICWMillOperation3::GetMinimumZ" method in the SolidworksCAM API.
38.	CW-85424	CSR-7750	Help	The Help description for the parameter of "Avoid small profiles" on Advanced tab of 3 Axis operation needs to be updated.



Sr. No.	CPR Number	Help Desk ID	Area	Description
39.	CW-85019	CSR-7477	Feature	For the specific part automatically recognized slot feature has incorrect depth value.
40.	CW-84539	CSR-7217	UIF	When incorrect post processor is selected then, the error message displayed needs to be improved.
41.	CW-82041	CSR-5596	Feature	For the specific turn part, incorrect part profile is generated when the part profile generation method is set to Revolved section.
42.	CW-78943	CSR-4430	Help	Add information on the "Avoid Areas" option to the milling Help documentation.
43.	CW-78921	CSR-4403	Operation	While using a dual spindle lathe, the lathe presets don't consider coordinate system at sub spindle setup, instead the Z preset considers Main spindle.
44.	CWR-1668	CSR-10674	Toolpath	For the Z level toolpath, when "Hognose" tool is used then it is observed that user cannot assign a negative allowance value more than the radius of the tool.
45.	CWR-1667	CSR-10372	Toolpath	For the specific part, when the 3 axis toolpath generation method is set to "Advanced Method" then, significant amount of time is taken to calculate the toolpaths.